7 Hovember 1952 (ATLANTIC BLALLE -P. TCO 4-3 Ed)

From: Chief, Merchant Vennol Inspection Division

To: Cant

Via: Chief, Office of Merchant Murine Safety

Subj. Farine Going of Investigation; collision, ATLANTIC DEALER with Gong PATCO and tow of tank barges. Delayare River, 22 May 1952, with loss of life.

- 1. Pursuant to the provisions of Title 46 C.F.R. Part 136, the record of the Marine Roard convened to investigate subject casualty, together with 113 Findings of Fact, Conclusions and Recommendations, has been reviewed and is forwarded herewith.
- The store tanker ATLANTIC MALER of 10,296 g. t., built in 1945 at Chester, Pa., owned by the Milantic Refining Company, departed from Port Arthur, Temas, with a full load of crude oil on board, destined for Philadelphia, while upbound in the Delawers River, the ATLANTIC Male R on the morning of 22 May 1952 approached Tinicum Range in mid or to the left of mid-channel at a speed of lk to 15 knots. On the same morning the motor tug PATCO of 105 g. t., towing the loaded tank barge PATOIL on the port side and the unloaded tank barge PATTURSON HO. 3 on the starboard side, departed dillingsport, W. J. downbound for Chester, in. This unidelity towing arrangement also approached Tiniom Range in mid or to the left of the channel. The weather was fine and clear with a light westerly breeze with ebb tide running at shout two knote. Indices Channel is approximately three miles in length and is subject to the Merrow Channel Rule, Article 25 (33 U.S.C. 210). Both vessels became confused with respect to the course and intentions of to other. Although collision-avoiding action was taken, the AMATTIC DIVALUE and the tank harge PATOIL alongside the port side of the tug PATCO collided, causing the tug to list sharply to starboard, ship water over her stern and sink. As a result of this casualty, three crew members on board the tug PATCO lost their lives by draming. Their names are as follows:

William C. John Hall.	License Chief	No.	•	Mester
Russell Ly	Cook		•	

- 3. The board made the following Findings of Fact:
- The tanker ATAMTIC NALUE and a tow composed of the tug PATCO and the tank barges PATTORSON NO. 3 and PATCIL were involved in a collision in Tinious Characl, Dolaware River, on 22 May 1952 at about 03th SST. As a result of the collision the teg and swamped and sunk with the loss of three even members. Others suffered injuries to a varying extent, none seriously. So esath or injury was suffered by any of the crew of the ATLANTIC DOLLER and her hull decays was slight. The PATCIL incurred an indentation in the hull where the bow of the DEALER came in contact, causing a displacement of framing and plating in the way of her starboard quarter.

- "2. The ATLUTIC DYALDR is a turbo-electric driven tank vessel, T-2, 6,000 h.p., of 10,296 gross tons, 50h' long, built in 1945 at Chester, Pa., the was bound from Fort Arthur, Texas to the Atlantic Refining Company pier at Fort Mifflin, Philadelphia, with a full load of crude oil in bulk and drawing an estimated 29.11' forward, 30.06' aft at the time of the collision. She is owned and operated by the Atlantic Refining Company, 260 S. Broad Street. Philadelphia. Pa., and was under the compand of the was acting in the dual capacity of master and pilot under the authority of his license. Her navigating gear had been in constant use during the veyage and was in good condition.
- "3. The PATCO, official number 249752, is a diesel driven uninspected tug of 105 gross tons, 68.3 long, built of steel materials at Houston, Texas in 1942. The tug and both barges are owned by the Terminal Transport Company. 213 South Broad Street, Philadelphia, but the tug was being operated by agent, of 1301 Cambridge Street, Camden, N. J. She was under the command of
- The PATT-RSON NO. 3, official number 174359, is a tank barge of 556 gross tone, 155° long, built at Pascagoula, Miss., in 1939. At the time of the collision she was light and her regularly assigned master was not on board, but she carried a dack hand, of the collision of the carried a dack hand, holds no seaman's documents of any kind.
- ms. The PATCHL, official number 173100, is a tank barge of 307 gross tons, 110.2' long, built of steel at Wilmington, Delaware in 1936. At the time of collision, this barge was fully leaded with

MVI 7 November 1952 (ATLANTIC DEALER - PATCO a-3 Bd)

low presence distillate and season board as master. Mr. holds a validated hardent bariner's document, indorsed for tankerman, all grades.

- sailed from Millingsport, N. J. for Chester, Pa. at about 02h5
 EST on 27 May 1952. The tow was made up with the tug between the
 two barges, the PATTIRSON NO. 3 on her starboard side, bow foremost and the PATTIRSON NO. 3 on her starboard side, bow foremost and the PATTIRSON NO. 3 on her starboard side, bow foremost and the PATTIRSON NO. 3 on her starboard side, bow foremost and the PATTIRSON NO. 3 and
 the CATOLL was nade fast to the bow of the PATTERSON NO. 3 and
 the tug was at the after end of the tow, in such a position that
 her stern protunded behind the vessels alongside.
- fine and clear, with a light westerly breeze and the collision was running with a velocity of about 2 knots. The DEALER was equipped with radar, in good operating condition, but it was not in use before or during the collision. Neither the PATCO nor the barges were so equipped.
- "8. Those who lost their lives as a result of the casualty were:

Master

John Rall,

Rossell Lynch,

- my. The testimony given by the witnesses from each vessel contains so many conflicting versions of signals, measurers and navigation, that the description of the events leading up to the collision are given with no attempt at reconciliation.
- "10. The ATLANTIC DEALER, fully loaded with crude oil, arrived at Delaware Presidenter on the evening of 21 May and proceeded up the Bay under the coun of her master. An uneventful passage ensued and Sun Shippard was passed at reduced speed at about 0300. Her engines were then rung full ahead as she entered the Eddystone Range. As she

channel, a down and tow, clearly lighted, was observed ahead on the starboard bow, abouting a grown side light at an estimated distance of a mile and a half to two miles.

- The signal was heard by any of her personnel. With the angle on the bow increasing slightly as the two vessels closed, another two blast signal was rounded, with no answering signal from the tow. Her engines were then put on a slow bell and at this point it was noticed that the tow had closed in the green light and was showing a red, and that the angle on the bow was rapidly decreasing. The engines were then stopped and rung full astern as it became apparent that the tow was swinging to her own starboard. A danger signal was sounded and the two blast signal repeated again and an answering danger signal, followed by one blast was heard from the tow. According to the DEALER's witnesses, the vessel was on a steady course until just before the collision, when the rudder was ordered full right, but none were of the opinion that her heading changed appreciably, since she was stopped or nearly so as the vessels collided.
- "12. The bow of the DEALER case in contact with the starboard bow of the PATOIL, and the tow passed down the port side of the DEALER. There was no sign of fire as the vessels separated, and the DEALER was anchored immediately. A lifehoat was launched and other vessels attracted to the scene searched for men in the water. Coast Guard patrol boats also appeared shortly after the collision, lending their efforts in the search.
- "13. According to the surviving witnesses from the tow, the PATCO, on leaving the dock at Billingsport, N. J. squared away in the channel and passed Tinicum Cas Sucy 5-T close on her starboard side as she proceeded down the channel. An inbound steamer was observed at the other end of Tinicum Channel showing a green side light, about a mile and a half away. The tow was proceeding at full speed with the full strongth of the cbb tide, but no one could give an intelligent estimate of her speed. A one blast signal was heard from the approaching vessel and a one blast signal was blown in answer, the rudder ordered right. As the vessels closed with no apparent change in headings, a four blast signal was blown followed by a single blast, and an answering one blast signal was beard from the vessel shead. The rudder was then ordered full right and the tow was swinging sharply when the collision occurred.

- the PATOIL, the care of the Wal R came into contact with the bow of the PATOIL, the care of the Ral R came into contact with the bow of bow to elevate, her stern to go down, and a heavy list to starboard, causing water to pour over her stern. The tug crew immediately left their stations and screebled aboard the barges as the tug swamped. As far as known, the engines were still on full ahead when she went down. The PATOIL drifted casy when her towing lines parted, but the PATOIRSON NO. 3 remained fast to the tug by one line. A later survey of the position of the sunken tug showed her to be 128° (T), 2,100 yards from Choster Range Rear Light, or approximately 300 feet north-westerly of the centerline of the channel. Several days later the tug was reised and showed little evidence of damage other than a collection of silt and mud.
- "15. As the vessels collided, the men at the wheel left the master lying on deck, the men on watch in the engineroom called the chief engineer, but made no attempt to do enything else as he ran out of the engineroom. Two crew members in the forecastle were awakened by the impact and both made attempts to get out of the starboard door. The surviving deck hand remembered the cock being behind him as he was swept away by the onrushing water."
- 4. The Board made the following Conclusions:
- "I. Although the testimony of the PATCO witnesses indicates cherwise, it is considered that she was navigating on her left hand side of the chemol and her presence there was the principal cause of the collision. Her failure to maintain a proper and efficient lookout, especially when the forward end of the tew was some distance ahead, with numerous deck obstructions to vision, was considered contributory.
- "2. The tog sank shout midway between the center line and northern edge of Tinicum Charnel and all her navigating crew, who survived, testified she was always on her own right hand side, and they also testified that the tow was being steered to the right at all times while being navigated in relation to the DEALER. First under an easy right and then a hard right rudder, the tow had been making a swing to starboard for three or more minutes before the collision.

Chiar, and a release we commended.

Had she be noted the right hand aide of the channel to begin with, this course change while have a raich her ashore north of the linicum Channel. The conclusion is invitably that she began her course change on the left hand side in ender to reach the point where she sank.

- "3. It is also considered that this was an unwieldy tow, a light and loaded blance on with relide, a condition that probably influenced the paster to place the top as far aft as possible to provide the greatest reduce effect. The position of the barges and the full strength of the solution, a leavestable current, may have added to the unwickliness and this condition should have been recognized by those on beard, at least to the extent of an elect watch and an efficient loakest.
- The testimony regarding the whistle signals heard by the PATCO witnesses was not considered adequate or acceptable. The wheelsman, who was also acting as mate, was a licensed engineer and had no independents for any deck rating. The master, who might have given more adequate testimony, was lost, but the wheelsman stated that he was in charge of the watch and the master about to turn in. Similar testimony was given by the man in charge in the enginerous, who was certificated as an ordinary comman.
- ment as to the signals sounded by their vessel and those heard from the PATCO. The testimony of the master of the DEALER, that he considered a starboard to starboard passing practical and possible without a change of course, was home out by the record of his course recorder which shows a steady course of COO COI for about three minutes before the collision. It further bears out the testimony of the DEALER witnesses that the way was off, or practically off, at the moment of impact, for the full astern movement imployed before the collision would have in all probability changed her heading had she gathered any stermay. It is therefore concluded that the DEALER did not change course and was approximately on the center line from the time she entered Timicum Channel. No logs or records of any kind were kept on the PATCO that here on her perfermance or navigation.
- "6. However, it is considered that the DEALER's navigation deserves comment. She had developed full speed as she entered the Tinicum Channel and maintained about 13 or 14 knots until no answer was heard to the second signal for the proposed passing. She was at or near the center line of the

Tinious Chancel at all times.

- and made an effort to navigate as required by the rules, the possibility existed that she might have avoided the collision by her action alone. However, under the conditions, where there was ample room for a clear passing, without a course change, and the master took her way off as soon as the proposed passing was in doubt, are considered circumstances supporting his judgment. Hence, the hypothetical port to port passing or a quick reduction in speed, are considered circumstances that only the master could cope with and at best are questions of judgment.
- Took notice of the conduct of the survivors of the PATCO after the collision. The mate at the wheel left the master lying on the deck where the force of the collision had thrown him. No effort was made to assist the fallen man in any way and his body was later found in the same place. The man on watch in the engine room never stopped to ascertain whether the sleeping chief engineer heard his warming; he left the ongine room with the engines on full speed and took no steps to assure himself of the safety of any others. Similar criticism can be leveled at the one survivor from the forecastle, but his action is ampliorated screwhat if his unsupported version of being swept sway by the rush of water is accepted.
- Motion was also taken of the lack of a master on board the PATTERSON NO. 3 at the time of the collision. However, since Captain of the PATCO, was licensed, it is considered there was no violation of the provisions of the certificate of inspection."
- 5. The Board made the following Recommendations:
- "1. Since the PATCO was an uninspected tag with no consequent requirements regarding certificated personnel; nor were those who had documents required to have them as a condition of employment, no action under R.S. 1450 is deemed advisable in these cases. And since there was no evidence of negligence or deliberate infraction of rules on the part of the DEALTR's personnel, no further action is recommended against them.

- It is recommended that the PATCO be cited for violation of Nule 25, of the Inland nules, (in that she fulled to navigate on her own right hand side of the channel).
- It is also recommended that the PATCO be cited for violation of Article 29 of the Inland frier, in that she failed to have a lookout.
- It is also recommended that the acting mate, Timer Robinson, be cital for violation of Rule 25 of the Inland Rules, in that he failed to navigate on his own right hand side of the channel; and it is further recorrended that he be cited for neglecting to post a proper lookout as required by Article 29, of the Inland Bules."

H. MARIES

- Conclusion 7 of the Sourd to the effect that had the navigation of ATLANTIC PHALER been in conformance with the statutory pilot raics she might have avoided the collision, is concurred with. The ATLANTIC DEALER in approaching Tinicum Range at a speed of 13 to 14 knots in mid or to the left of mid-channel did not conform with the precautions required by ordinary practices of seamen under the circumstances and violated the Narrow Channel Rule (33 V.S.C. 210) and thus contributed to the cause of the subject collision.
- Recommendation paragraph 3 of the Board that the PATCO be cited for violation of article 29 of the Inlend aules in that she failed to have a lookout is presently disapproved. The subject is being carefully reviewed and studied, in the light of recent judicial decisions to determine whether or not the statetory pilot rules authorize the assessment and collection of civil menetary penalties for the neglect to keep a proper lookout. Pending such determination, action to assess and collect civil memorary penaltics for neglect to keep a proper lookout should be held in abevance.
- Recommodation paragraph is of the Board to the effect that civil monetary penalties be assessed against the mate on watch on board the tug PATCO at the time subject casualty occurred for violation of Rule 25 and Article 29 of the Inland Bules, is also disapproved. The evidence in the record clearly indicates that the navigation of the tag PATCO was in charge of the master of the vessel immediately prior to the collision, as a result of which the master perished by drowning.
- Subject to the foregoing remarks. It is recommended that the Findings of Fact, Conclusions, and Recommendations of the Murine Board of Investigation be approved.

/B/P. A. OVENDEN

P. A. OVERDEN

Chief, NVI Division to Commandant

MVI 7 November 1952 (ATLANTIC DEALER - PATCO a-3 Bd)

FIRST EMPORSEM OF TO MVI memorandum of 7 November 1952

24 November 1952

Prom:

Chief, Office of Merchant Murine Safety

To:

Commandant

Subje

Marine Board of Investigation; collision, ATMANTIC DEALTH with tug PATCO and tow of tank barges, Delaware River, 22 May 1952, with loss of life

Forwarded, recommending approval.

/a/H. C. SHEPHEARD H. C. SHEPHEARD

APPROVED: Nov 25 1952

/s/ MERLIN O'NEILL MERLIN O'NEILL Vice Admiral, U.S. Coast Guard Commandant