

Date of issue: September 2018

## SAFETY BULLETIN 12 - Accidental CO<sub>2</sub> releases onboard 2 UK Merchant Vessels

## The Issue

The Maritime & Coastguard Agency is aware of two serious and potentially near fatal accidental  $CO_2$  releases on UK ships in the last two years. In both cases the  $CO_2$  leaked from the manifold into the  $CO_2$  room. In both cases the remote release valves were untouched and the  $CO_2$  alarms operated, alerting the crew and averting fatalities. However, these incidents follow a concerning pattern of similar incidents. The MCA would like to remind operators that  $CO_2$  is highly asphyxiating, a 9% concentration causes unconsciousness within minutes and 17% causing death within just a couple of minutes.  $CO_2$  is also both colourless and odourless.

## **Key findings of a recent MAIB investigation:**

- Many systems are designed such that a single leaking valve can discharge the entire system.
- Lack of clarity on life/service intervals and maintenance requirements of cylinder valves.
- There is perceived over reliance on shore-based contractors who may have poor knowledge of the specific system fitted onboard.
- CO<sub>2</sub> leaked from the systems and was not contained by the pipework and manifold.



Image - Common arrangement of pilot bottles connected to system with flexible pipes

Some key areas that should be highlighted which will reduce the risk of reoccurrence of similar incidents;

• When bottles are required to be refilled, it is important that valves should be either serviced or replaced at least in line with manufacturers recommendations. With

- regards maintenance of the valves the MCA and MAIB would like to draw the attention of service agents and ships operators to BS EN ISO 22434:2011 Transportable gas cylinders Inspection and maintenance of cylinder valves which provides relevant guidance on the issue of maintenance where manufacturers are silent on the issue.
- MCA interpretation of MSC.1/Circ.1318 requires that 10% of high pressure CO<sub>2</sub> cylinders are hydrostatically tested at their 10 year anniversary. Furthermore, in line with BS EN 1968-2002 All remaining cylinders must be hydrostatically tested by the 20 year anniversary.
- Flexible pipework must be replaced at intervals specified by the manufacturer or at the 10 year anniversary whichever is sooner as per MSC.1/Circ.1318.
- The IMO FSS Code, chapter 5.2.1.1.3 requires that crew should be checking quantities of fire extinguishing medium. Given the numbers of bottles involved, methods such as weighing of cylinders are highly impractical. There are now commonly available simple methods such as ultrasonic liquid level gauges which facilitate easy in situ level testing which operators should consider in order that their crews can readily and safely check the levels of CO<sub>2</sub> thus enabling early detection of a potential problem. The UK would consider this appropriate as per the IMO FSS Code Chapter 5.2.1.1.3 and this could be built into the planned maintenance system.
- The MCA would remind operators of the benefit of marking the cylinders and checking CO<sub>2</sub> levels at least annually.
- The MCA would also recommend that operators test and ensure the correct operation of any pressure switches and alarms within their systems.

## **Further information**

For further information please contact <a href="marinetechnology@mcga.gov.uk">marinetechnology@mcga.gov.uk</a> or phone on +44 2038 172000