



U.S. COAST GUARD EIGHTH DISTRICT
GULF OF MEXICO OUTER CONTINENTAL SHELF
MARINE SAFETY INFORMATION BULLETIN
LIFEBOAT OPERATIONS ON MANNED FACILITIES



MSIB 19-04

24 July 2019

On June 30, 2019, a floating offshore facility experienced a tragic accident with loss of life while exercising their lifeboat in accordance with their regularly scheduled maintenance and training plan. In the process of retrieving the lifeboat, while the lifeboat was level with the facility's loading deck and personnel were transitioning from the lifeboat back onto the facility, an incident occurred causing the lifeboat and personnel to fall approximately 75 feet to the water.

A Coast Guard investigation to determine causal factors that contributed to this incident is ongoing. Because the potential factors involved in this incident may be common to many facilities on the Outer Continental Shelf (OCS), immediate and positive action need not await the results of the investigation. It is recommended that all owners, operators, and masters immediately complete the following:

- Review the company's maintenance procedures for lifeboats and ensure they adhere to manufacture criteria for the model and make of lifeboats, davits, and other installed lifesaving equipment.
- Take a proactive approach to ensure your personnel are properly trained in the inspection, maintenance and use of their lifesaving equipment.

Operators are also encouraged to review USCG D8(ocs) Policy Letter 04-2016, Rev 1 titled "Inspections of Emergency Evacuation Drills on Manned Facilities with Lifeboats (Boats)" and contact the District 8 OCS Officer in Charge, Marine Inspection (OCMI) office at 504-671-2106 or OCSCorrespondence@uscg.mil should they desire to pursue an alternative to lifeboat loading in the Gulf of Mexico.

Sincerely,

A handwritten signature in blue ink that reads "R E Holmes".

R. E. HOLMES
Captain, U. S. Coast Guard
Eighth District Outer Continental Shelf
Officer in Charge, Marine Inspection