

Ship Name: **BAHAMAS PEARL**

Ship Type: **Bulk Carrier**

Flag: **Panama**

IMO Number: **9356347**

Date of Action: **3/20/2025**

Action Taken: **Detention**

Port: **Miami, Florida**

Unit: **Sector Miami**

Recognized Org: **Isthmus Bureau of Shipping**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Class Related**

Relevant Certificates: **SOLAS Cargo Ship Safety Constru**

Organization Related
to Detention: **Isthmus Bureau of Shipping**

Ship Management: Owners, Operators, or Managers

MMS Americas LLC

Centauri Transport, LLC

Deficiencies: Code - Category

**15109 - Maintenance of the ship and
equipment**

**01102 - Cargo Ship Safety
Construction (including exemption)**

Description

The company should establish procedures to ensure that the ship is maintained in conformity with the provisions of the relevant rules and regulations and with any additional requirements which may be established by the company. Due to the objective evidence in the below deficiencies, the vessel is not in substantial compliance with relevant conventions, calling into question the adequacy and implementation of the vessel's SMS under the ISM code. PSCO's collected objective evidence that the vessel could not produce evidence that the company notified Flag Administration of the serious safety deficiencies, IBS acted on behalf of flag without administration approval. External audit required.

A certificate called a Cargo Ship Safety Construction Certificate shall be issued after an initial or renewal survey to a cargo ship which complies with the relevant requirements of Chapters II-1 and II-2 (other than those relating to fire safety systems and appliances and fire control plans) and any other relevant requirements of the present regulations. PSCO's found SOLAS Safety Construction Certificate expired on January 20, 2025.

This deficiency is considered RO Related.