

Ship Name: **ADRE**
Ship Type: **Bulk Carrier**
Flag: **Liberia**

IMO Number: **9575199**

Date of Action: **4/10/2025**

Action Taken: **Detention**

Port: **Wilmington, North Carolina**

Unit: **Sector North Carolina**

Recognized Org: **Lloyd's Register**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related
to Detention:

Ship Management: Owners, Operators, or Managers
Spring Vall Shipping Mgmt
Huihe (Tianjin) Shipping Leasing Co Ltd

Deficiencies: Code - Category

13199 - Other (machinery)

**07109 - Fixed fire extinguishing
installation**

**07126 - Oil accumulation in engine
room**

11104 - Rescue boats

Description

Boilers shall be provided with means to supervise and control the quality of the feedwater. Suitable arrangements shall be provided to preclude, as far as practicable, the entry of oil or other contaminants which may adversely affect the boiler; vessel's cascade tank has fuel oil intrusion. Tank must be free from petroleum products and prima facie evidence must be provided that waterside of boiler is free from petroleum products.

Machinery spaces of category A above 500 m3 in volume shall, in addition to the fixed fire-extinguishing system required in paragraph 5.1.1, be protected by an approved type of fixed water-based or equivalent local application fire-extinguishing system; vessel's hypermist system failed to operate in incinerator and purifier room when tested by PSCO and Flag State Inspector.

Means shall be provided to control leaks of flammable liquids; several leaks on main engine, #2 Generator and fuel boost pump for main engine in purifier room.

(See Team: def different from Form B)

Before the ship leaves port and at all times during the voyage, all life-saving appliances shall be in working order and ready for immediate use; crew was unable to keep rescue boat running when directed by PSCO to start.