

Ship Name: **MARIANNA I**

Ship Type: **Containership**

Flag: **Liberia**

IMO Number: **9162227**

Date of Action: **4/4/2025**

Action Taken: **Detention**

Port: **Baltimore, Maryland**

Unit: **Sector Maryland-NCR**

Recognized Org: **RINA Services S.p.A.**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related
to Detention:

Ship Management: Owners, Operators, or Managers

Technomar Shipping Inc

Kimi Maritime LLC

Deficiencies: Code - Category

**15108 - Reports of non-conf.,
accidents & hazardous occur.**

Description

The safety management system should include procedures ensuring that non-conformities, accidents and hazardous situations are reported to the company. PSCO discovered that the master failed to notify the company/COTP, without delay, regarding the fuel oil leak in cargo hold number 2. The technical and/or operational nature of deficiencies 02 and 03 provide objective evidence of a serious failure, or lack of effectiveness, of the implementation of the ISM Code. A safety management audit carried out by the Administration or the RO, with a corresponding report of findings satisfactory to the OCMI must be submitted prior to clearance of this deficiency and release from detention.

This deficiency is NOT RO related.

**15101 - Safety and environment
policy**

The technical operational nature of deficiencies 01, 03, and 04 provide objective evidence of a serious failure, or lack of effectiveness, of the implementation of the ISM Code. A safety management audit carried out by the Administration or the RO, with a corresponding report of findings satisfactory to the OCMI must be submitted prior to clearance of this deficiency and release from detention.

This deficiency is NOT RO related.