

Ship Name: **TRABZON**

Ship Type: **Bulk Carrier**

Flag: **Malta**

IMO Number: **9595046**

Date of Action: **7/29/2025**

Action Taken: **Detention**

Port: **Mobile, Alabama**

Unit: **Sector Mobile**

Recognized Org: **Lloyd's Register**

Recognized Security  
Organization (RSO):

Recognized Org  
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related  
to Detention:

Ship Management: Owners, Operators, or Managers

**Ciner Gemi Acente Isletmeleri Sanayi ve  
Ticaret AS (Ciner Ship Management)**

**Trabzon Maritime Ltd**

Deficiencies: Code - Category

**10114 - Voyage data recorder  
(VDR)/Simplified Voyage data  
recorder(S-VDR)**

Description

**The Administration shall be satisfied that adequate  
arrangements are in place to ensure that the  
performance of the equipment required by this chapter is  
maintained. PSCOs observed objective evidence that the  
vessel's VDR was inoperable due to showing an error.  
Captain and electrician were unaware of the location of  
the error source. When checking the VDR's manual,  
PSCOs discovered the error resulted in the VDR not  
communicating properly and recording the data  
required by**