

Ship Name: **TINTO**

Ship Type: **General Dry Cargo Ship**

Flag: **Dominica**

IMO Number: **7369168**

Date of Action: **8/27/2025**

Action Taken: **Detention**

Port: **Miami, Florida**

Unit: **Sector Miami**

Recognized Org: **International Naval Surveys Bureau**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Class Related**

Relevant Certificates: **SOLAS Cargo Ship Safety Constru**

Organization Related **International Naval Surveys Bureau**
to Detention:

Ship Management: Owners, Operators, or Managers
Maritime Management AS
Tinto Shipping Ltd

Deficiencies: Code - Category

01102 - Cargo Ship Safety
Construction (including exemption)

Description

The structure, machinery and equipment of a cargo ship as referred to in paragraph (b)(i) shall be subject to the surveys and inspections specified below: A minimum of two inspections of the outside of the ship's bottom during any five-year period, except where regulation 14(e) or (f) is applicable.

The interim CSSCC issued by INSB on 27JUL2025 lists the last two inspections of the ship's bottom as 05DEC2022 and 18MAY2020. The vessel could not provide documentation demonstrating that the ship's bottom has been inspected.

This deficiency is RO associated