

Ship Name: **ZIM IBERIA**

Ship Type: **Supply Ship**

Flag: **Liberia**

IMO Number: **9431719**

Date of Action: **8/19/2025**

Action Taken: **Detention**

Port: **Elizabeth, New Jersey**

Unit: **Sector New York**

Recognized Org: **Det Norske Veritas**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related
to Detention:

Ship Management: Owners, Operators, or Managers

Zim Integrated Shipping Services Ltd

Zim Iberia LP

Deficiencies: Code - Category

**07126 - Oil accumulation in engine
room**

**15109 - Maintenance of the ship and
equipment**

Description

Means shall be provided to control leaks of flammable liquid. PSCO's observed excessive oil pooling in purifier room beneath mixing tank and #1/#2 heating units, degraded lagging between mixing tank piping and main engine line, and active oil leaks between the flow meter and flanges below #1/#2 heating units.

The company should establish procedures to ensure that the ship is maintained in accordance with the provisions of the relevant rules and regulations established by the company. Deficiencies above provide objective evidence of a serious failure of the implementation of the ISM CODE. An External Audit Report satisfactory to the Captain of the Port must be submitted prior to the clearance of the deficiency.