

Ship Name: **GLADIATOR**

Ship Type: **Bulk Carrier**

Flag: **Marshall Islands**

IMO Number: **9445033**

Date of Action: **10/23/2025**

Action Taken: **Detention**

Port: **Chesapeake, Virginia**

Unit: **Sector Virginia**

Recognized Org: **Nippon Kaiji Kyokai**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related
to Detention:

Ship Management:

Deficiencies: Code - Category

**15109 - Maintenance of the ship and
equipment**

**07123 - Operation of Fire protection
systems**

Description

THE COMPANY AND THE SHIP SHALL COMPLY WITH THE REQUIREMENTS OF THE ISM CODE. THE COMPANY SHOULD ESTABLISH PROCEDURES TO ENSURE THAT THE SHIP IS MAINTAINED IN CONFORMITY WITH THE PROVISIONS OF THE RELEVANT RULES AND REGULATIONS. THE COMPANY SHOULD ENSURE; APPROPRIATE CORRECTIVE ACTION IS TAKEN. PSCO OBSERVED, DURING AN EXPANDED EXAM, THE FOLLOWING: FAILURE OF THE COMPANY AND SHIP TO PROPERLY MANAGE FAILING CO2 PIPING AND SUPPORT BRACKETS. AN EXTERNAL ISM AUDIT IS REQUIRED PRIOR TO RELEASE FROM THE DETENTION.

FIRE-FIGHTING SYSTEMS AND APPLIANCES SHALL BE KEPT IN GOOD WORKING ORDER AND READILY AVAILABLE FOR IMMEDIATE USE. PSCO OBSERVED HOLE IN CO2 LINE ON THE PORT SIDE FORWARD CORNER ALONGSIDE CARGO HOLD #5 AND SEVERAL BROKEN CO2 LINE BRACKETS RENDERING THE SYSTEM INOPERABLE FOR CARGO HOLD #4.