

Ship Name: **OLYMPIC SPIRIT**

Ship Type: **Chemical Tankship**

Flag: **Liberia**

IMO Number: **9327097**

Date of Action: **11/25/2025**

Action Taken: **Detention**

Port: **Wilmington, North Carolina**

Unit: **Sector North Carolina**

Recognized Org: **Det Norske Veritas**

Recognized Security  
Organization (RSO):

Recognized Org  
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related  
to Detention:

Ship Management: Owners, Operators, or Managers

**DYNAMIC SHIPMANAGEMENT SA-LIB**

**OLYMPIC SPIRIT SHIPPING S.A.**

Deficiencies: Code - Category

**15113 - Other (ISM)**

**02134 - Loading/Ballast condition**

Description

**The company and the ship shall comply with the requirements of the International Safety Management Code. The technical nature of deficiencies 02, 03, and 04 provide objective evidence of a serious failure, or lack of effectiveness, of the implementation of the ISM Code. Additionally, the SMS A safety management audit carried out by the Administration or the RO, with a corresponding report of findings satisfactory to the OCMI must be submitted prior to clearance of this deficiency and release from detention.**

**The ship's load line shall not be submerged at any time when the ship puts out to sea, during the voyage, or on arrival. The primary load line reference was found submerged by approximately 10-15 cm. Review of the departure drafts, fuel burn rate, current trim, and crew statements confirmed that the load line was submerged during transit. Correct the overloaded condition and review current procedures and loading calculations to ensure load line limits are continuously maintained and not exceeded during future cargo operations.**