

Ship Name: **AM PURPOSE**

Ship Type: **Bulk Carrier**

Flag: **Marshall Islands**

IMO Number: **9455387**

Date of Action: **6/23/2026**

Action Taken: **Detention**

Port: **Norfolk, Virginia**

Unit: **Sector Virginia**

Recognized Org: **American Bureau of Shipping**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related
to Detention:

Ship Management: Owners, Operators, or Managers
**Selandia Ship Management (Singapore) Pte
Ltd**
AM Purpose Limited

Deficiencies: Code - Category

**15109 - Maintenance of the ship and
equipment**

**07123 - Operation of Fire protection
systems**

Description

The company and the ship shall comply with the requirements of the ISM Code. The company should establish procedures to ensure that the ship is maintained in the conformity of the provisions of the relevant rules and regulations and with any additional regulations which may established by the company. The technical and/or operational nature of deficiency 02 provides objective evidence of a serious failure, or lack of effectiveness of the implementation of the ISM code. A safety management audit carried out by the Administration or the RO, with a corresponding report of findings satisfactory to the OCMI must be submitted prior to clearance of this deficiency and release from detention.

Fire-fighting systems and appliances shall be kept in good working order and readily available for immediate use. PSCO observed inoperable emergency fire pump and excessive leakage from the shaft packing gland and priming box.