

Ship Name: **SILVER SKY**

Ship Type: **Ro-Ro-Cargo Ship**

Flag: **Panama**

IMO Number: **9448140**

Date of Action: **6/3/2025**

Action Taken: **Detention**

Port:

Unit: **Sector Columbia River**

Recognized Org: **American Bureau of Shipping**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Not Class Related**

Relevant Certificates: **SOLAS Cargo Ship Safety Constru**

Organization Related
to Detention: **American Bureau of Shipping**

Ship Management: Owners, Operators, or Managers

Mi-Das Line SA

Sallaum Lines DMCC

Deficiencies: Code - Category

15107 - Emergency preparedness

Description

THE COMPANY SHOULD ESTABLISH PROCEDURES TO ENSURE THAT THE SHIP IS MAINTAINED IN ACCORDANCE WITH THE PROVISIONS OF THE RELEVANT RULES AND REGULATIONS ESTABLISHED BY THE COMPANY. THE TECHNICAL AND OPERATIONAL NATURE OF THE DEFICIENCIES NOTED BELOW PROVIDE OBJECTIVE EVIDENCE OF A SERIOUS FAILURE OF THE IMPLEMENTATION OF THE ISM CODE. AN EXTERNAL AUDIT REPORT SATISFACTORY TO THE COAST GUARD MUST BE SUBMITTED PRIOR TO CLEARANCE OF THIS DEFICIENCY.