

Ship Name: **PALANCA RIO**

Ship Type: **Chemical Tankship**

Flag: **Marshall Islands**

IMO Number: **9747998**

Date of Action: **1/20/2026**

Action Taken: **Detention**

Port: **Baltimore, Maryland**

Unit: **Sector Maryland-NCR**

Recognized Org: **American Bureau of Shipping**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related
to Detention:

Ship Management: Owners, Operators, or Managers
Executive Ship Management Pte Ltd
N.C.N. Corporation

Deficiencies: Code - Category

15109 - Maintenance of the ship and equipment

Description

The company should establish procedures to ensure that the ship is maintained in conformity with the provisions of the relevant rules and regulations. The technical and operational nature of deficiencies 2,3,4,5,6 and 7 provide objective evidence of a serious failure, or lack of effectiveness, of the implementation of the ISM Code. A safety management audit carried out by the Administration or the RO, with a corresponding report of findings satisfactory to the OCMI must be submitted prior to clearance of this deficiency and release of detention.

07109 - Fixed fire extinguishing installation

Fire protection systems and fire-fighting systems and appliances shall be maintained ready for use. PSCO observed 14 unauthorized temporary repairs on the vessels high pressure water-mist piping system, with 02 active leaks while in operation. Additionally, PSCO observed the ships crew conducted a water mist system inspection on 17OCT2025 including inspection of all piping for damage/corrosion without any indication of unauthorized temporary repairs.

09209 - Electrical

Electrical installations shall be such as to minimize the risk of fire and explosion from flammable product. PSCO observed 02 exposed wires on electrical sensor component near cargo discharge pump in the vessel's pump room.