

Ship Name: **ICE GRACE**

Ship Type: **Refrigerated Cargo Carrier**

Flag: **Bahamas**

IMO Number: **8706777**

Date of Action: **2/1/2023**

Action Taken: **Detention**

Port: **Philadelphia, Pennsylvania**

Unit: **Sector Delaware Bay**

Recognized Org: **Lloyd's Register**

Recognized Security  
Organization (RSO):

Recognized Org  
(RO) Related: **Class Related**

Relevant Certificates: **Safety Management Certificate**

Organization Related  
to Detention: **Lloyd's Register**

Ship Management: Owners, Operators, or Managers  
**Carpe Marine Group S. A.**  
**Acheon Akti Navigation Co. Ltd**

Charterers  
**Cool Carriers Ltd**

Deficiencies: Code - Category

**15109 - Maintenance of the ship and equipment**

**07106 - Fire detection and alarm system**

Description

**In meeting these requirements, the company should ensure that: inspections are held at appropriate intervals; any non-conformity is reported, with it's possible cause, if known; appropriate corrective action is taken; and records of these activities are maintained. Objective evidence discovered during an expanded ISM exam revealed that the vessel failed to properly inspect and maintain critical fire safety appliances including fixed fire detection, fire doors, and fire extinguishers. Additionally, these long-standing non-conformities have not been properly reported or addressed in accordance with the vessel's safety management system. An external third party audit is required.**

**Any required fixed fire detection and fire alarm system with manually operated call points shall be capable of immediate operation at all times. PSCO observed four fire detectors in the engine room with rags secured around them and one that was dismantled rendering them unavailable for immediate operation. Four additional detectors have been inoperable since October 2022.**