

Ship Name: **ONEGO GLOMMA**
Ship Type: **General Dry Cargo Ship**
Flag: **Antigua and Barbuda**

IMO Number: **9294977**

Date of Action: **8/26/2025**

Action Taken: **Detention**

Port: **Lake Charles, Louisiana**

Unit: **Marine Safety Unit Lake Charles**

Recognized Org: **Nippon Kaiji Kyokai**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related
to Detention:

Ship Management: Owners, Operators, or Managers

**TAS Transatlantische Schifffahrts GmbH &
Co KG**

ms 'Onego Glomma' GmbH & Co KG

Deficiencies: Code - Category

**15104 - Masters responsibility and
authority**

**07125 - Evaluation of crew
performance (fire drills)**

Description

The company should clearly define and document the master's responsibility with regard to: 1. implementing the safety and environmental-protection policy of the company. 2. motivating crew in the observation of that policy. The operational nature of deficiencies 02,03 04 and 05. provide objective evidence of a serious failure of the implementation of the ISM Code. An external audit report, satisfactory to the OCMI must be submitted, prior to clearance of this deficiency.

Each fire drill shall include: .3 checking of fireman's outfits and other personal rescue equipment; 4. checking of relevant communication equipment. PSCO observed 02 fire drills conducted. Fire team was unable and unaware on proper donning of SCBA. Lack of communication between the fire team and bridge and lack of knowledge of fire fighting equipment located in galley.