

Ship Name: **EMIL SELMER**

Ship Type: **Bulk Carrier**

Flag: **Portugal**

IMO Number: **9559705**

Date of Action: **9/27/2025**

Action Taken:

Port: **Juneau, Alaska**

Unit: **Sector Southeast Alaska**

Recognized Org: **Det Norske Veritas**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related
to Detention:

Ship Management: Owners, Operators, or Managers
Oskar Wehr KG. (GMBH & Co.)
SELMER BULK SHIPPING LTD.

Deficiencies: Code - Category

07199 - Other (fire safety)

11104 - Rescue boats

Description

Fire fighting systems and appliances shall be kept in good working order and readily available for immediate use. PSCO observed following deficiencies: 1) Emergency fire pump did not provide any water to the bridge wing fire hose station. 2) Multiple fire hoses (08), are deteriorated; numerous pin hole leaks and gasket failures on hoses located on deck (port & stbd bridge wings, c deck, upper deck, cargo deck area and engine room. 3) 02 fire stations (engine room) do not have spanner wrenches at hose station.

Before the ship leaves port and at all times during the voyage, all life saving appliances shall be in working order and readily available for immediate use. PSCO observed the following: rescue boat is not able to start.