

Ship Name: **PANAMAX OSTRIA**

Ship Type: **Bulk Carrier**

Flag: **Liberia**

IMO Number: **9399557**

Date of Action: **10/1/2025**

Action Taken: **Detention**

Port: **New Orleans, Louisiana**

Unit: **Sector New Orleans**

Recognized Org: **RINA Services S.p.A.**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related
to Detention:

Ship Management: Owners, Operators, or Managers
Wisdon SA

Deficiencies: Code - Category

**07109 - Fixed fire extinguishing
installation**

**04103 - Emergency,
lighting, batteries and switches**

15113 - Other (ISM)

Description

Firefighting system and appliances shall be kept in good working order and readily available for immediate use. PSCO observed fixed local water suppression system turned off and water supply valve in the closed position.

The electrical power available shall be sufficient to supply all of those services that essential for safety in emergency. PSCO observed crew unable to energize emergency lighting.

The company should establish procedures to ensure that the ship is maintained in accordance to the provisions of the relevant rules and regulations established by the company. The technical and operational nature of the deficiencies 01 and 02 above provide objective evidence of a serious failure of the implementation of the ISM Code. An external audit report to the satisfactory of the OCMI must be submitted prior to the clearance of this deficiency.