Ship Name: VOYAGER

Ship Type: Supply Ship

Flag: Honduras

IMO Number: 9069700

Date of Action: 10/2/2025

Action Taken: Detention

Port: Miami, Florida

Unit: Sector Miami

Deficiencies: Code - Category

10111 - Charts

Recognized Org: CONARINA

Recognized Security Organization (RSO):

Recognized Org (RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related

to Detention:

Ship Management: Owners, Operators, or Managers

Ducker AGG

Description

All snips, irrespective of size, shall have: nautical charts and nautical publications to plan and display the ship's route for the Intended voyage and to plot and monitor positions throughout the voyage. An electronic chart display and information system (ECDIS) is also accepted as meeting the chart carriage requirements of this subparagraph. Ships to which paragraph 2.10 applies shall comply with the carriage requirements for ECDIS detailed therein:.5 back-up arrangements to meet the functional requirements of subparagraph .4. if this function Is partly or fully fulfilled by electronic means. PSCO's observed the vessel having one method of electronic charting which is not up to date, does not meet the requirements set fourth in IMO Res. A.817(19) and does not have a means for updating. Additionally the vessel has no secondary means of navigation. The Caribbean Cargo Record of

Equipment states the vessel has no ECDIS or method of electronic charting.