

Please review the following pictures taken during actual exams and decide, based on the space; (a) what is the category of the space, (b) is the way in which the space is living equivalent to that in which it was designed, (c) if a deficiency does exist, to what regulation would you write the deficiency, and; if further amplifying information is required to make a determination, what questions would you ask. For the sake of this exercise, the ship has a keel lay date of august 1st 2010. Please forward your responses to Jason Yets, at jason.m.yets@uscg.mil. Your comments will be made non-attributional and posted to our internal USCG discussion forum for all our marine inspectors to see, all comments provided to us will be listed as “from industry” only.

A/C Room



Forward passenger stair-tower landing



Medical quarantine room



Provisions area



Deck dept stowage locker



Passenger corridor



Bosun store

